

EFFECTIVENESS OF TYRE CHIPS AS
ALTERNATIVE MATERIAL IN INCLINED
GABION WALL TO MITIGATE SLOPE
FAILURE

MUHAMAD WAFIY BIN IDZANI

B. ENG(HONS.) CIVIL ENGINEERING

UNIVERSITI MALAYSIA PAHANG



SUPERVISOR'S DECLARATION

I/We* hereby declare that I/We* have checked this thesis/project* and in my/our* opinion, this thesis/project* is adequate in terms of scope and quality for the award of the Bachelor Degree of Civil Engineering.

(Supervisor's Signature)

Full Name : DR. AMIZATULHANI BINTI ABDULLAH

Position : SENIOR LECTURER

Date : 25 JUNE 2018



STUDENT'S DECLARATION

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at Universiti Malaysia Pahang or any other institutions.

(Student's Signature)

Full Name : MUHAMAD WAFIY BIN IDZANI

ID Number : AA14097

Date : 25 JUNE 2018

EFFECTIVENESS OF TYRE CHIPS AS ALTERNATIVE MATERIAL IN
INCLINED GABION WALL TO MITIGATE SLOPE FAILURE

MUHAMAD WAFIY BIN IDZANI

Thesis submitted in fulfillment of the requirements
for the award of the
Bachelor Degree in Civil Engineering

Faculty of Civil Engineering and Earth Resources
UNIVERSITI MALAYSIA PAHANG

JUNE 2018

ACKNOWLEDGEMENTS

Firstly, I would like to thank God for His greatness, give the ideas, energy, and dedication to me for complete this Final Year Project course.

I would like to express my highest sincere appreciation to my supervisor Dr. Amizatulhani Binti Abdullah for her valuable supervision, continuous encouragement, cooperation and guide me to the right direction in making this research a success. Her wide knowledge, experiences and skills in the has allowed me to perform better and sharpen my capabilities in many areas, especially in the field of Geotechnical Engineering.

I would also like to thank all the lab assistants in Soil and Geotechnics Laboratory, Universiti Malaysia Pahang, En. Ziunizan, En. Nor Azmi and En. Haliman who provided me trainings and equipment during my laboratory testing to complete my project. Next, I want to thank all my friends for their support, guidance, sharing and suggestions throughout my research, as their helps are important for the completeness of this project.

Finally, thank you to my family members especially my parents and the special one: Idzani Bin Ibrahim and Saudah Binti Awang for their love, moral supports and encouragement in completing this research work.

ABSTRAK

Kegagalan cerun adalah masalah biasa di negara-negara tropika seperti Malaysia, yang dipengaruhi oleh geografi tropika, profil cuaca dan kelembapan udara. Faktor utama kegagalan cerun adalah disebabkan oleh hujan lebat kerana lazimnya kegagalan cerun sering berlaku selepas hujan lebat. Tembok penahan adalah struktur yang dapat mengekalkan tanah di belakangnya dari menggeser atau mengikis. Jenis dinding penahan yang paling mudah ialah dinding gabion. Dinding gabion adalah dinding yang terbuat dari jaring dawai yang disusun diikat bersama dan diisi dengan kelikir. Walau bagaimanapun, penggunaan batu kelikir dalam tembok gabion perlu dikurangkan kerana penggalian batu kelikir berbahaya kepada persekitaran. Oleh itu, penyelesaian untuk mengurangkan penggunaan kelikir di tembok gabion adalah dengan menggabungkan kelikir dengan bahan lain. Tayar terpakai adalah bahan sesuai untuk digabungkan dengan kelikir bagi mengisi dinding gabion dengan nisbah peratusan tertentu. Dalam kajian ini, model cerun akan diuji dengan beberapa nisbah kelikir bercampur cip tayar yang akan diisi ke dinding gabion bagi menahan cerun pasir bersudut 60° yang di simulasi hujan buatan berintensiti 570mm/h. Dari hasil kajian, 50% Kelikir dicampur dengan 50% cip tayar sebagai bahan ganti untuk dinding gabion mampu menahan bagi mencegah kegagalan cerun bagi model berskala kecil kerana dari hasil kajian, berbezaan pergerakan dinding gabion 50% Kerikil dicampur 50% cip tayar dengan 100% kerikil hanya 6%.

ABSTRACT

Slope failure is a common problem in tropical countries such as Malaysia, which is characterised by tropical region, weathering profile and a humid. The main factor of slope failure is caused by heavy rain because normally slides often occur after intense rainfall. A retaining wall is a structure that can retain soil behind it from sliding or eroded away. The most convenient type of retaining wall is gabion wall. A gabion wall is walls made of stacked wire meshes tied together and filled with gravel. However, the use of gravel in gabion needs to be decreased because the gravel quarrying is harmful to the environment. Thus; the solution to decrease usage of gravel in gabion wall is by combine the gravel with other material. Used tyres were chosen to combine with gravel that will fill up the gabion wall with certain percentage ratio. In this study by using slope model and simulation several of ratios that filled up in to gabion wall are tested against the sand slope with 60° angle that subjected artificial rainfall with intensity 570mm/h. From the result of the study, 50% Gravel mixed with 50% tyre chip as material for gabion wall is strength enough to prevent slope failure and provide support for vertical or near-vertical grade for small-scale model because the difference between current practices by using 100% gravel is only 6%

TABLE OF CONTENT

DECLARATION

TITLE PAGE

ACKNOWLEDGEMENTS **ii**

ABSTRAK **iii**

ABSTRACT **iv**

TABLE OF CONTENT **v**

LIST OF TABLES **viii**

LIST OF SYMBOLS **xi**

LIST OF ABBREVIATIONS **xii**

CHAPTER 1 INTRODUCTION **1**

1.1 Background of Study **1**

1.2 Problem Statement **3**

1.3 Objective of Study **4**

1.4 Scope of Research **4**

CHAPTER 2 LITERATURE REVIEW **5**

2.1 Malaysia's Climate/Weather **5**

2.2 Introduction to Slope Failure **7**

2.3 Mode of Slope Failure **8**

2.3.1 Fall Failure **11**

2.3.2 Topple Failure **12**

2.3.3 Slide Failure **13**

2.3.4	Spread Failure	14
2.3.5	Flow Failure	14
2.4	Cases of Slope Failure in Malaysia	15
2.5	Current Practice/Method to Ensure Stability of Slope	17
2.5.1	Gravity Wall	18
2.5.2	Gabion Walls	19
2.5.3	Cantilever Walls	21
2.6	Waste Tyres	23
2.7	Tyres Recycling Activities	24
2.7.1	Thermal Insulation Process	24
2.7.2	Waste Tyres in House Construction	26
CHAPTER 3 METHODOLOGY		30
3.1	Introduction	30
3.2	Research Flow Chart	31
3.3	Laboratory Test	32
3.3.1	Sieve Analysis	32
3.3.2	Specific Gravity Test	33
3.3.3	Standard Proctor Test	34
3.3.4	Constant Head Permeability Test	35
3.4	Preparation of Material	36
3.5	Development of Slope Model	37
3.6	Digital Transducer	39
CHAPTER 4 RESULTS AND DISCUSSION		42
4.1	Introduction	42

4.2	Laboratory Test Results	43
4.2.1	Sieve Analysis	43
4.2.2	Particle Density Test and Specific Gravity Test	46
4.2.3	Standard Proctor Test	48
4.2.4	Constant Head Permeability Test	53
4.3	Slope Model Result	54
CHAPTER 5 CONCLUSION		58
5.1	Introduction	58
5.2	Conclusion	58
5.3	Suggestions and Future Study	60
REFERENCES		61
APPENDIX A Laboratory work permit		65

LIST OF TABLES

Table 2.1	Monsoons rainfall contributions in Paninsular Malaysia	7
Table 4.1	Specific gravity of sand	46
Table 4.2	Table of discription of sample	46
Table 4.3	Weight of percentage gravel and tyre chips sample	47
Table 4.4	Specific Gravity of each mixture sample	47
Table 4.5	Optimun water contain and maximun dry unit weight	52
Table 4.6	Coefficient of permeability for each mixture sample	53

LIST OF FIGURES

Figure 1.1	Landslide at the Cameron Highlands-Sungai Koyan road	2
Figure 1.2	Top View of landslide at the Cameron Highlands-Sungai Koyan road	2
Figure 2.1	Box and whisker plot of areal average mean monthly rainfall	6
Figure 2.2	Passive and active earth pressure	8
Figure 2.3	Types of landslide. Abbreviated version of Vernes' classification	10
Figure 2.4	Type of slope movement	11
Figure 2.5	Fall Falling Slope Failure of slope	12
Figure 2.6	Slide failure of slope	13
Figure 2.7	Spread slope failure of slope	14
Figure 2.8	Example of debris flow type	15
Figure 2.9	Apartment at Highland tower was collapses due to slope failure	16
Figure 2.10	Reported landslides and fatalities 1973-2007	17
Figure 2.11	Retaining wall type	18
Figure 2.12	Typical failure mechanisms for a gravity walls	19
Figure 2.13	Permeability of gabion elements	21
Figure 2.14	Cantilever retaining wall	22
Figure 2.15	Failure mechanism for cantilever retaining wall.	23
Figure 2.16	Typical 'Earthship' side view	26
Figure 2.17	Typical 'Earthship' floor plan	27
Figure 3.1	Size of perspex frame	36
Figure 3.2	Perspex frame was filled with sand	37
Figure 3.3	Inclined arrangement of gabion wall	38
Figure 3.4	Average monthly precipitation in Kuantan, Malaysia	39
Figure 3.5	Digital transducer was used to measure the movement	40
Figure 3.6	Digital transducer was used to measure the movement of gabion wall	40
Figure 3.7	Output of readout device	41
Figure 4.1	Particle size distribution curve of sand	44
Figure 4.2	Particle size distribution curve of gravel	45
Figure 4.3	Particle size distribution curve of tyre chips	45

Figure 4.4	Compaction curve of sand	48
Figure 4.5	Compaction curve of 100% gravel and 0% tyre chips sample	49
Figure 4.6	Compaction curve of 80% gravel and 20% tyre chips sample	49
Figure 4.7	Compaction curve of 60% gravel and 40% tyre chips sample	50
Figure 4.8	Compaction curve of 50% gravel and 50% tyre chips sample	50
Figure 4.9	Compaction curve of 40% gravel and 60% tyre chips sample	51
Figure 4.10	Compaction curve of 20% gravel and 80% tyre chips sample	51
Figure 4.11	Compaction curve of 0% gravel and 100% tyre chips sample	52
Figure 4.12	Compaction curve of all samples	52
Figure 4.13	Coefficient of permeability against percentage of gravel	54
Figure 4.14	Displacement of slope without gabion wall	55
Figure 4.15	Displacement of gabion wall against time for 100% Gravel	56
Figure 4.16	Displacement of gabion wall against time for 50% Gravel	56
Figure 4.17	Displacement of gabion wall against time for 0% Gravel	57
Figure 4.18	Displacement of gabion wall against time three samples	57

LIST OF SYMBOLS

γ_d	Dry Density
γ	Bulk Density
ω	Water Content
c_u	Coefficient of Uniformity
c_c	Coefficient of Gradation
G_s	Specific Gravity
%	Percentage

LIST OF ABBREVIATIONS

NEM	North West Monsoon
SWM	South West Monsoon
OLR	Outgoing Longwave Radiation
PWD	Public Works Department
EPA	Environmental Protection Agency
WBCSD	The World Business Council for Sustainable Development

CHAPTER 1

INTRODUCTION

1.1 Background of Study

Slope failure is a common problem in tropical countries such as Malaysia, which is characterised by tropical region, weathering profile and a humid. The main factor of slope failure is caused by heavy rain because normally slides often occur after intense rainfall. A few months ago, heavy rains over the past few days triggered a landslide on the Cameron Highlands-Sungai Koyan road at 2.30pm on February 2018 but no loss of life or injury was reported, and that no vehicles were involved in the incident. Even though no loss of life or injury the government needs to spend lots of money to restore the damages. So, slope stability is very important to decrease risk of injury and damages restoring cost. Aside from assessing and monitoring existing slopes, whether man-made or natural, another important consideration when it comes to slope stability is proper slope design. Successful slope design requires the gathering of information regarding the site's geology and characteristics (e.g. the properties and status of rock mass, soil, and groundwater in and around the excavation), interpretation of this information, and the development of a design that takes this information into account. For this study, gabion types of retaining wall will be used. Gabion by definition is a cage filled with rocks, concrete, or sometimes sand and soil. A gabion wall is a retaining wall made of stacked stone-filled gabions tied together with wire. Gabion walls are usually angled back towards the slope, or stepped back with the slope, rather than stacked vertically. For this study, instead of stones only, a mixture of tyre chips and stones will be used to fill the gabion wall.



Figure 1.1 Landslide at the Cameron Highlands-Sungai Koyan road
Source: m.thestar.com.my/



Figure 1.2 Landslide at the Cameron Highlands-Sungai Koyan road
Source: www.nst.com.my

1.2 Problem Statement

Slope failure is a common phenomenon in tropical countries such as Malaysia, which is characterised by tropical region, weathering profile and a humid. The main factor of slope failure is caused by heavy rain because normally slides often occur after intense rainfall. This is because water is commonly the primary factor triggering a landslide. When storm water runoff saturates soils on steep slopes or when infiltration causes a rapid rise in ground water some slopes become unstable and fail. In addition, slope failure also due to uncontrolled development especially at hilly geographic area such as Cameron Highlands, Ulu Klang, and Serendah. The landslide tragedies have killed many people and also destroy the facilities such as buildings, roads, houses, bridges and others. This phenomenon also enforces the government to spend lots of money to restore the damages. As a result, preventing and reducing landslide effect can be solved by using retaining wall.

A retaining wall is a structure that can hold soil behind it from sliding or eroded away. There are many types of retaining wall structure. The most convenient type of retaining wall is gabion wall. A gabion wall is walls made of stacked wire mesh tied together and fill with gravel. To protect the all hill that has probability to fail around Malaysia, a lot of gravel required to fill up in gabion wall. However, application gravel in gabion needs to be decrease because the gravel quarrying is harmful to environment. For example, gravel quarries immediate ecological damage, destroy forest land and take away the habitats of animals. The gravel is typically produced through drilling and blasting the rock to make it smaller for specific uses. Through drilling and blasting rock, it will increase the noise pollution, air pollution, damage the habitat and biodiversity destruction. One of solution to decrease usage of gravel in gabion wall is by combine the gravel with other material.

Nowadays, dumping used tyres represent a serious environmental problem in Malaysia. The study shows that emissions from the burning of tyres are a serious threat to human health. The toxins released from tyre decomposition may cause irritation, respiratory and skin problems. Meanwhile, used tyre also become mosquito breeding places and spread dengue fever brought by Aedes mosquitoes which listed as the most frequent disease in Malaysia recently. Used tyres were chosen to combine with gravel

REFERENCES

- Terzaghi, K., 1950. *Mechanism of landslides , Application of Geology to Engineering Practice (Berkey Volume)*, Geological Society of America. 1st ed. New York: S. Paige (Ed.)
- Brand, 1981. *Thoughts on Rainfall Induced Slope Failures* *Proceedings of 10th International Conference on Soil Mechanics and Foundation Engineering*, Stockholm: E.W.BrandSome.
- R.K. Regmi, K. Jung, H. Nakagawa, J. Kang, 2014. *Study on mechanism of retrogressive slope failure using artificial rainfall Catena*,
- B. M. Das, 2009. *Principles of Foundation Engineering, chapter 7 Lateral Earth Pressure. In: Principles of Foundation Engineering*. Ed. H. Gowans. Global Engineering.
- B. James, 2011. *Dimensionering kring spont. Jämförelse mellan fältmätningar och FEM-simuleringar*. MA thesis. Luleå tekniska universitet, Institutionen för samhällsbyggnad och naturresurser.
- G. Rnajan, 2000. *Basic and applied soil mechanics second edition. In: Basic and applied soil mechanics*. Ed. A. R. Daryaganj.
- P.M. Kandar, 1999. *Use of gabions for localized slope stabilization in difficult terrain.*, The 37th U.S. Symposium on Rock Mechanics (USRMS), pp 1221-1227, Vail, Colorado.
- Stead, D., and Coggan, J., 2012. *Numerical modeling of rock slope stability. In Clague, J.J., and Stead, D. (Eds.), Landslides: Types, Mechanisms and Modeling*: Cambridge University Press, New York, NY, 420 p.
- Clayton C.R.I., Milititsky J., Woods R.I., 1993. *Earth Pressure and Earth Retaining Structures*, Spon Press, Taylor and Francis Group, 2nd Edition , pp. 155-161.

Duncan, J. M., and Wright, S. G., 2005. *Soil Strength and Slope Stability: John Wiley and Sons*, Hoboken, NJ, 297 p.

Lu, N., Godt, J. W., and Wu, D. T., 2010. *A closed-form equation for effective stress in unsaturated soil: Water Resources Research*, Vol. 46, No. 5, 14 p.

Nash, D. F. T., 1987. *A comparative review of limit equilibrium methods of stability analysis. In Anderson, M.G., and Richards, K.S. (Eds.), Slope stability-geotechnical engineering and geomorphology, John Wiley and Sons*, New York, NY, pp 11-76.

Moten, S.: *Multiple time scales in rainfall variability, Proc. Indian Acad. Sci. (Earth Planet. Sci.)*,

Wong, C. L., Venneker, R., Uhlenbrook, S., and Jamil, A. B. M, 2009. *Large-scale variability of rainfall: creation and analysis of a new daily gridded data set for Peninsular Malaysia, International Conference on Water Resources (ICWR 2009) Langkawi, Malaysia*,.

Chang, C. P., Harr, P. A., and Chen, H. J, 2015. *Synoptic disturbances over the equatorial South China Sea and western maritime continent during boreal winter*, *Mon. Weather Rev.*, 113, 489–503.

Murakami, T, 1980. *Temporal variations of satellite-observed outgoing longwave radiation over the winter monsoon region. Part I: Long-period (15–30 day) oscillations*, *Mon. Weather Rev.*, 108, 408–426, 1980.

Cheang, B. K, 1997. *Synoptic features and structures of some equatorial vortices over the South China Sea in the Malaysian region during the winter monsoon, December 1973*, *Pure Appl. Geophys.*, 115, 1303–1333,

Tangang, F. T., Juneng, L., Salimum, E., Vinayachandran, P. N., Kok Seng, Y., Reason, C. J. C., Behera, S. K., and Yasunari, T. 2008. *On the roles of the northeast cold surge, the Borneo vortex, the Madden Julian Oscillation, and the Indian Ocean Dipole during the extreme 2006/2007 flood in southern Peninsular Malaysia*, *Geophys. Res. Lett.*, 35, L14S07, doi:10.1029/2008GL033429

Ramage, C. S, 1964. *Diurnal variation of summer rainfall of Malaysia*, J. Trop. Geogr., 19, 62–68, .

M. Mukhlisin, I. Idris, A. S. Salazar, and K. Nizam, 2010. *GIS based landslide hazard mapping prediction in Ulu Klang, Malaysia*, ITB J. Sci., vol. 42, no. 2, pp. 163– 178,

Jamaludin S, Ali F, 2011. *An overview of some empirical correlations between rainfall and shallow landslides and their applications in Malaysia*. Electron J Geotech Eng 16:1429–1440

M. Azmi, J. Kiyono, 2011. and A. Furukawa, “*Earthquake-induced landslide analysis for Batu Feringghi, Penang,*” in Proceedings of the 31st Conference on Earthquake Engineering, p. 5.

Thiruvangodan, S. K., 2006. *Waste Tyre Management in Malaysia, PhD Thesis, Faculty of Environmental Studies, University Putra Malaysia*

United States Environmental Protection Agency 1997. EPA-600/R97-115; pg ii – x

Imperial Innovations Quelle, 2008. *In search for a better technique to recycle waste tyre into new tyre*, www.recyclingportal.eu retrieved 16.7.2012

Aniza A. A. & Rao S P., 2012. *Overview of the advantages and disadvantages of recycle, reuse, reclaim & recovery of waste tyres; proceedings in ASEAN Post Graduate Seminar*, UM, Kuala Lumpur, Malaysia; pp 358 –372

Dhir R.K., Limbachiya M C. and Paine K. A. (editors); 2001. *Recycling and Reuse of Used Tyres*; Thomas Telford Publ., London

Garg, K. G., 1997. Stabilisation of slopes in Garhwal Himalaya, Proceedings of Geosynthetics Asia '97, Bangalore, India, pp. A.27 - A.34

Ferriolo F., Vicari, M., Kulkarni, T. P. and Gharpure, A. D., 1997. *Landslide road protection and river training works with gabion structures, Proceedings of Geosynthetics Asia '97, Bangalore, India*, pp. 11.13 - 11.20

Bergado, D. T., Chai, J. C. and Miura, N., 1995. *FE analysis of grid reinforced embankment system on soft Bangkok clay*, *Computers and Geotechnics*, Vol. 17, pp. 447 - 471